

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/17/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 07/12/12 – 0700, 07/19/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
1100	<p>Helicopter safety briefing. Take off.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • Source area pond nearly dry. • Observed Talmadge Creek restoration work. • Frac-Tank City: observed boom being decontaminated. • Ceresco Dam boom: maintenance/sheen sweep boat observed at C0.4 boat launch. • Railroad trestle above Ceresco Dam: observed sheen on downstream side. Operations was notified. • Observed Ceresco Dam portage work. • Ceresco Dam: observed debris removal from the control point. • Ceresco Dam sheen observed. Sheen was generated from the boom maintenance boat. • Ceresco Dam: observed decibel monitoring station. • Flight back up river, observed sheen sweep boat at MP5.25 LDB. • MP5.25: Sheen: observed along LDB behind the sheen sweep boat. • MP8.25: RI crew observed. • MP9.75 RDB: sheen observed. • MP15.5 South Mill Pond, no sheen observed. • Sheen sweeper boat observed at MP 21.5. • MP28.25: decibel monitoring station. • Morrow Lake Delta: poling crew just west of 35th Street Bridge. • Morrow Lake Delta: poling crew observed. • Morrow Lake Delta: observed boom maintenance along Boom B. • Morrow Lake Delta: sheen observed along Boom A. • Morrow Lake: observed sweep boat operating south of Rowe Island. 		
	Additional observations: None		
1230	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			